uppliance centre · WILLISTON, NORTH DAKETA SE NON Serial +4667 70 3/ Gestomer claim, the rifle went off while operating the bolt on three different commions during bunting this past weekend. The third time was while he was attempting to unload the rifle near his pickup and the rifle discharged sending the bullet thre the front-seet of the treek aid then thre the floor board hitting the frame an then back up thru the floor boards. You may want to send the fifte into Amington since the oustoner is very wehappy about the damage to his company truck, and believes the rifle malfanctioned. .. Ibsak you. D. W. Mess owner. BIGNED

TEGIPIENT KEEP THIS COPYRETURN WHITE COPY TO SENDE

SOURCE FREE FREEFERS SAFFER ENGINEERS AND AND AND ASSESSED IN THE TREE PROPERTY AND ADDRESS AND ADDRES

Examination of the rifle and trigger assembly could not duplicate the incident that was described. All parts tolerances and dimensions were found to be normal, including sear-connector engagement. Also, factory seals were intact on the trigger adjustment screws, indicating no alterations were made on the trigger outside our company. Trigger pull was within our specifications at 34 pounds.

Based on our findings, Remington Arms Company, Inc., cannot accept any liability or responsibility for the incident. We can only assume that as your customer operated the bolt, he inadvertently brushed, or hit, the trigger which caused the rifle to fire.