LIFE INSURANCE the State Farm way!

RALPH E. CUMMINGS
Auto-Life-Health-Home and Business
P O BOX 809; 406 ROANOKE ST
CHRISTIANSBURG, VA 24073 PHONE (703) 382-5552

December 6, 1988

Arms Service Division
Remington Arms company,Inc.
Ilion, New York 13357

RE: Remington Rifle
Caliber 30.06
Model 700LH BDL
Serial #B6367915

Gentlemen,
I have a problem somewhere in the safety or bolt section of this rifle [redacted] think.
As I tried to fire it with the safety fully forward in the fire position the trigger would not move (as if it were still on safety). I put as much pressure on the trigger as I dared and still it wouldn't fire. I thought maybe the cartridge wasn't locked in right so I ejected it and advanced another one into the barreland still I got the same results.when I tried to fire it again,using even more trigger presure this time.

With the safety in the fire position and my finger off the trigger I started to move the bolt for another ejection when the rifle fired.It fired at the very first movement of the bolt.After that it did fire normal although the first normal firing had a rough trigger pull.

It may be working right now but something for sure is wrong.

Please repair or replace the parts you find caused this and please call or write me once you have determed the problem.
Thanks for your help.

Sincerely,
Ralph E Cummings

P.S.
In getting this rifle ready for shipment to you I stripped the screws in the front scope mount. Please repair them and replace them with new ones. They are made by Redfield. Thanks.

[redacted]