RECEIVING AND ESTIMATING REPORT

COMMENTS: BOTTOM HALF OF MTS ONLY Stekl

ORDER: R 92-05628

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
02/13/92	02/19/92	RI 11-76	A6379500		700 22-250 BDL

ACCESSORIES: W/STUDS SCOPE BASE L/SIGHTS

FROM:
VAN LEUNENS
DBA ALL ABOUT SPTS
621 WILMER AVE
CINCINNATI OH 45226

SHIP TO:
VAN LEUNENS
DBA ALL ABOUT SPTS
621 WILMER AVE
CINCINNATI OH 45226

CUST NO:008341 WILM

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		3-11-92	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	When	B2 you	push	Safety	E1 forward	F1 gun fires
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: As received, rifle was inoperative — could not cock when bolt was closed — firing pin would simply follow-down on cocking cycle. Disassembly revealed connector was broken — reason could not be established

PARTS

COMMENTS: Replace trigger assembly at no charge as gesture of customer good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
RBB					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/9