T.P. 4 3/4
4 1/2
4 3/4

Sear Cut .011 5

Excessive Lube On Assy. (WD-40) Trig Pull Adjusted Outside Of Factory Appears To Have (over)

ENTS

AL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
6558525		700 270
E		

SHIP TO:

GRIMM, MATT
102 BRYSON
LIBERTY HIL

TX 78642

CUST NO:090698 C.O.D.

WRITE ☐

PROM. DATE	ESTI

☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT
CYCLE	A1	B1			
TRIGGER GROUP		B2			E1
BOLT ASSY.		B3			E2
BARREL ASSY.		B4		D1	E3
REC. ASSY.		B5		D2	E4
WOOD			C1	D3	E5
METAL			C2		

MAIN FAULT

Excessive Lube On Trig Assy - Trig Adjus
Factory - Trig Assy Sealant Not Rem.

PARTS

COMMENTS

Replace Trig As
As A Gesture Of (
Test & Return

REPAIRMAN	PROOF	CLEAN	TF
GALLERY TESTER	DATE	DATE	D/

OFFICE COPY