RECEIVING AND ESTIMATING REPORT

COMMENTS: Stekl

ORDER: R92-00507

INITIAL: LCS

CUSTOMER ORDER NO.:

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/30/91	01/07/92	XE. 12-84	B6638383		700 270 ADL

ACCESSORIES: W/STUDS SCOPE BASE L/SIGHTS

FROM:
SERVISTAR SPORTSMAN REPAIR
& HARDWARE
7045 PARKLANE RD
COLUMBIA SC 29204
USA

SHIP TO:
SERVISTAR SPORTSMAN REPAIR
& HARDWARE
7045 PARKLANE RD
COLUMBIA SC
USA 29204

CUST NO:028775 ILION

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		1-23-92	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	Fires	when	Safety	is	Released	
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Rifle will malfunction as described in attached letter. Disassembly of rifle revealed that trigger assembly contains internal rust and trigger and sear will remain in pulled condition due to binding of rust. Internal parts not moving nor functioning properly.

PARTS:

COMMENTS: Replace trigger at no-charge, as a gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
P B S					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

REV. 8/91

PPS 04435