RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 91-25984

INITIAL	CUSTOMER ORDER NO.
LCS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/10/91	12/12/91	PF 6-85	B6712840		700 6MM BDL

ACCESSORIES W/STUDS SCOPE BASE

FROM:
TATUM, JULIEN
PO BOX 603
UNIVERSITY MS 38677
USA

SHIP TO:
TATUM, JULIEN
135 LEIGHTON RD
OXFORD MS
USA 38655

CUST NO:054693 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

1.) "... on occasion this rifle will discharge while pushing the safety from the on position to the off position."
2.) accuracy is unacceptable 3"-4" groups at 100 yards

MAIN FAULT 1.) Inside of trigger assembly has somehow become rusted. Internal trigger parts are not moving freely nor properly.
2.) Rifle will have to be gallery tested to determine.

PARTS

COMMENTS
1.) Replace trigger assembly at no-charge as gesture of good-will.
2.) Have gallery test accuracy of rifle

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PAT
GALLERY TESTER	DATE	DATE	DATE	DATE	DAT

OFFICE COPY

RD6925 RE

PPS 04999