RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 94-19601

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
06/22/94	06/23/94	DR 9-68	367791		700 308 WIN BDL

ACCESSORIES

L/STUDS, REAR SIGHT

Setup file

FROM:

ADAMS, JOHN M., JR.
7815 BELFORD DR.
COLORADO SPRINGS CO 80920

SHIP TO:

ADAMS, JOHN M., JR.
7815 BELFORD DR.
COLORADO SPRINGS CO 80920

CUST NO:099125 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
					UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	20.0
EXCISE	
TAX	
INSURANCE	
UPS	8.00
PARCEL POST	
TOTAL	28.0

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP ✓		B2				
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4				F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT Spontaneous discharges of the rifle when the bolt was closed & the safety was moved to fire. Upon receipt, we could not duplicate the customer concern. However, examination revealed that the 1968 manufactured rifle has been poorly maintained. The bolt stop release, trigger assembly, and action are covered in a heavy buildup of dirt and debris & lubricant. Heavy scratching marks are on the trigger housing and full length of the sear assembly.

PARTS

#26345

COMMENTS

Replace the complete trigger assembly and clean action (bolt parts) at 1/2 normal replacement / repair cost to gesture good will. Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

EA/S
8/2/94

PS00297