RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 92-02928

STEKL

INITIAL	CUSTOMER ORDER NO.
FPS	073502

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
01/16/92	01/23/92	LI 2-88	C6238707		700 22-250 BDL

ACCESSORIES W/STUDS SCOPE BASE L/SIGHTS

FROM:
GEM SPORTS SUPPLY CO.
625 BURNETT AVE.
SYRACUSE NY 13203

SHIP TO:
GEM SPORTS SUPPLY CO.
625 BURNETT AVE.
SYRACUSE NY 13203

CUST NO:004064 ILION

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		2-10	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1 goes	B1 off on safety				
TRIGGER GROUP	goes	B2 off putting safety on			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT As received, rifle would not cock, & disassembly of rifle revealed that the trigger assembly has been improperly adjusted outside factory (as evidenced by red sealant on sear-engagement screws) — insufficient sear engagement

Trigger pull 2# — well below minimum spec.

PARTS

COMMENTS Send quotation for replacement trigger assembly at ½ normal costs gesture of good-will.

Note — w/ an customer about adjusting triggers outside factory

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
BWJ					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91

PS02730