KENNETH N. JONASEN
P. O. BOX 111
ULM, MONTANA 59485

March 30, 1994

Remington Arms Co
Arms Services Division
14 Hoefler Avenue
Ilion, New York 13357

Attention: Jerry

In regard to our telephone conversation on March 25, 1994, I am sending you my Remington Model 700 30-06 SPRG (Springfield), Serial Number: 251152 for your inspection.

As I explained in our conversation, the gun discharged on 2 separate occasions when a bullet was placed into the chamber and the safety was pushed forward. Needless to say, I am glad we are very careful with weapons, and no injury occurred.

Both instances were witnessed by Wayne Morin and myself. I have lost all confidence in this rifle, and hopefully, you will make a satisfactory adjustment. I do not feel comfortable with a repair, and if this is done, I will hold your company fully responsible for this defect in the event an accident reoccurs.

I have other Remington rifles that I have used more often than this one and have never had this problem.

I am anticipating cooperation from Remington Company with my problem.

Sincerely,

Kenneth N. Jonasen
P. O. Box 111
Ulm MT 59485

Shipping address: 801 Second Street South
Great Falls, MT 59401

Phone: (Work) 406-453-9442
(Home) 406-866-3512

GALLERY TESTER
PROOF
CLEAN
TEST
DATE
OFFICE COPY