RECEIVING AND ESTIMATING REPORT

COMMENTS: CLASSIC

ORDER: R 92-18643

INITIAL	CUSTOMER ORDER NO
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE	
09/04/92	09/16/92	PC 6-82	B6395478		700 257	ROBERTS

ACCESSORIES: W/STUDS SCOPE BASE

FROM:
ROSE'S SPORTING GOODS
RD 2 BOX 193
BOSWELL PA 15531

SHIP TO:
ROSE'S SPORTING GOODS
RD 2 BOX 193
BOSWELL PA 15531

CUST.NO:005670 WILM

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		CLEAN/TEST			UPS

GUN CONDITION
- [ ] NEW
- [x] LIGHTLY WORN
- [ ] WORN
- [ ] VERY WORN
- [ ] UNREPAIRABLE
- [ ] MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

In one instance the rifle fired when the safety was released. In another instance, after firing, when the bolt was closed.

MAIN FAULT: Unable to duplicate either of the above complaints. The rifle and trigger assembly operated properly in every respect, and could not be made to malfunction.

Trigger pull 3½ pounds, sear lift .0105"

PARTS

COMMENTS: After the action of trimming the rifle is-do, B1 of replacing trigger assembly at $4 nominal cost as a gesture of good will, if that will better restore confidence in the rifle.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTE
NLC					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV.

PS05062