RECEIVING AND ESTIMATING REPORT

COMMENTS: STEKL

ORDER R 92-14659

INITIAL	CUSTOMER ORDER NO
JJM	K12769

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
07/08/92	07/17/92	WI 8-88	C6279986		700 243 ADL

ACCESSORIES: W/STUDS

FROM:
SPORTS WORLD
5800 S LEWIS STE 154
ATTN T L DENTON
TULSA OK 74105

SHIP TO:
SPORTS WORLD
5800 S LEWIS STE 154
ATTN T L DENTON
TULSA OK 74105

CUST NO:005259 WILM

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		7/24/92	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1 1) Stock cycled by bolt	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.	2) When fired shows it sometimes release firing pin causing				E2	F2
BARREL ASSY.		B4 accidental firing of round.		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Trigger assembly is completely gummed up with WD-40. Internal trigger parts are not moving freely for properly. Warn owner of gun not to use WD-40 on this type!!

PARTS

COMMENTS: Offer new trigger assembly at ½ normal cost, as gesture of good will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
LRD					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1/9

PS05885