May 24, 1980

Gentlemen,

Enclosed you will find two 600 Mohawk rifles which have gone off as the bolt is locked forward.

We understand you have had problems with this model and that you put on a different trigger assembly.

The one went off in my house, ruined the barrel of another gun on the wall, which caused metal pieces to fly around the room. One person was injured. It could have been a very fatal case.

Thank you,

Bob Bangs
Campo, Colorado
81029

17469 — FIRE FIGHTING EQUIPMENT DISCHARGES FORWARD

COMPLAINT:

INCIDENT:

COMMENTS: Sear lift .007. Sear & Safety cam has sluggish action due to gummy substance on these parts. This condition could have contributed to incident.

Replace trigger assembly.