RECEIVING AND ESTIMATING REPORT

ORDER R91-24362

INITIAL	CUSTOMER ORDER NO.
LCS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/22/91	11/26/91	KI 5-88	C6251170		700 30-06 ADL

ACCESSORIES W/STUDS SCOPE BASE L/REAR SIGHT

FROM:
HILLS INC
1720 CAPITAL BLVD
RALEIGH NC 27604
USA

SHIP TO:
HILLS INC
1720 CAPITAL BLVD
RALEIGH NC
USA 27604

CUST NO:004393 ILION

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		12-9	UPS

GUN CONDITION
- ☐ NEW
- ☒ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

marred

REPAIR CHARGE
EXCISE
TAX
INSURANCE
UPS
PARCEL POST
TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1			E1	F1
TRIGGER GROUP		B2			E2	F2
BOLT ASSY.		B3			E3	F3
BARREL ASSY.		B4		D1	E4	F4
REC. ASSY.		B5		D2	E5	F5
WOOD			C1	D3		
METAL			C2			

fired 3 times when safety is put in fire position, without pulling trig

MAIN FAULT Trigger assembly rusted from unknown source — internal parts not moving freely nor properly — trigger retraction not consistent nor positive. Problem could not be duplicated, but with corrosion of trigger assembly, malfunction could occur.

PARTS	COMMENTS
	Replace trigger assembly at no-charge, as gesture of good-will

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTE
BWT					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY RD6925 REV.