RECEIVING AND ESTIMATING REPORT

COMMENTS: Steel

ORDER: R92-16016

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
07/31/92	08/11/92	RX 11-73	6685506		700 7MM MAG LH BDL

ACCESSORIES: W/STUDS L/SIGHTS

FROM:
ROPER, JOHN
2284 CODY ESTEY RD
RHODES MI 48652

SHIP TO:
ROPER, JOHN
2284 CODY ESTEY RD
RHODES MI 48652

CUST NO:064663 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER NO.	WRITE	PROM. DATE	ESTIMATED	VIA
		CLEAN/TEST		8-19-92	UPS

GUN CONDITION
- [ ] NEW
- [ ] LIGHTLY WORN
- [ ] WORN
- [ ] VERY WORN
- [ ] UNREPAIRABLE
- [ ] MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A	B1				
TRIGGER GROUP	Gun	B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Rec'd. Trigger assembly is inoperative. Trigger assembly is contaminated with gummy-sticky residue, rear safety cam and other internal trigger parts all sticking to trigger assembly and plate are not moving. This condition appears to have resulted from improper maintenance. Customer has all adjustments out of specifications

PARTS

COMMENTS: Offer new trigger assembly at 5 normal cost as gesture of good-will since customer has mis-adjusted present trigger assembly.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTE
RBS					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1