RECEIVING AND ESTIMATING REPORT

H93-17685

W/PACHMAYR RECOIL PAD

INITIAL	CUSTOMER ORDER NO.	DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
FPS		08/20/93	08/25/93	84	B6626691		700 270 WIN ADL

ACCESSORIES SCOPE BASE

FROM:
SATIN SEAR PISTOLSMITH
424A PECAN DR.
ALEDO TX 76008

SHIP TO:
SATIN SEAR PISTOLSMITH
424A PECAN DR.
ALEDO TX 76008

CUST NO:082651 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐		9-9-93	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL						

Defective trigger block.

MAIN FAULT

Please to inspect customer comm. Remarks. Manufacturer should state all 3 adjustment screws have lost the contact ground, causing they have lost tension with outside the safety. Condition of bolt not cycling when open, is correct, as first, but is after 1984 after adjustment screws to engage.

PARTS

COMMENTS

Replace trigger assembly & bring adjustment back to factory specs of good work.

Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	P/
C C		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	D

OFFICE COPY

RD69251