| FAULT CATEGORY | OLD CODE | NEW CODE | MALFUNCTIONS |
|---|---|---|---|
| OUT OF SPECS | M047 | M217 | OVER LOCKED |
| OUT OF SPECS | | M218 | PREPLAY ON SEAR NOT TO FACTORY SPECIFICATIONS |
| MISCELLANEOUS | | M219 | CARDBOARD PACKING RING WAS NOT REMOVED |
| MISCELLANEOUS | | M220 | PISTON/PISTON SEAL INCORRECTLY INSTALLED |
| OUT OF SPECS | | M221 | RECEIVER FEED CUTS ARE ROUGH |
| MISCELLANEOUS | | M222 | MODIFY TUBE CAPACITY TO ACCEPT 10 ROUNDS |
| BROKEN PART | | M223 | ACTION TUBE RING BROKEN |
| OUT OF SPECS | M059 | M224 | BREECH PLUG FROZE IN BREECH |
| BROKEN PART | M030 | M225 | EJECTOR SPRING IS BROKEN |
| OUT OF SPECS | | M226 | FORE END TUBE NUT IS LOOSE - FORE END RUBS BARREL |
| BROKEN PART | M061 | M227 | GAS BLOCK SEPARATED FROM BARREL |
| BROKEN PART | | M228 | GUIDE RING SEPARATED FROM BARREL |
| OUT OF SPECS | | M229 | MAGAZINE GUIDE IS OUT OF POSITION |
| BROKEN PART | | M230 | LOCKING BAR ASSEMBLY BROKEN |
| OUT OF SPECS | | M231 | NIPPLE NOT TO FACTORY SPECIFICATIONS |
| OUT OF SPECS | | M232 | RECEIVER INSERT IS MISSING |
| OUT OF SPECS | M055 | M233 | RESIZE BORE |
| BROKEN PART | M036 | M234 | RECEIVER BROKEN AT BARREL CLAMP |
| OUT OF SPECS | M055 | M235 | RESIZE BORE |
| BROKEN PART | M036 | M236 | RECEIVER BROKEN AT BARREL CLAMP |

CONFIDENTIAL

Subject to Protective Order - Williams v. Remington