Re: F.D. COLE
P# 76-23601
Return received

December 5, 1986

CREDIT BUREAU OF DUBLIN
C/O JAMES R. JONES, JR.
123 HIGH STREET
P.O. BOX 1947
DUBLIN, GEORGIA 31040

Dear Mr. Jones:

Examination has been completed on the model [illegible], 308 Win caliber rifle, serial number 121614, which you submitted to us because "the rifle fired even when being [illegible]".

The referenced firearm, which was produced in August 1968, has been thoroughly examined to determine the cause of the reported malfunction. [illegible] the trigger mechanism [illegible] upper left side of the trigger.

The general condition of the rifle appears to be very good, but it was noted the stock was worn some from use [illegible] and grease. In addition, it was noted the rifle had been extensively [illegible], stock re-worked, [illegible] re-blued, [illegible] scope mounting [illegible], high [illegible], [illegible] [illegible] found [illegible]

[illegible]