RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 92-00006

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/20/91	01/02/92	ER 10-68	376577		700 30-06 ADL

ACCESSORIES W/STUDS SCOPE BASE L/SIGHTS

FROM:
FRED'S GUN EMPORIUM
3003 SLIDE RD
LUBBOCK TX 79407
USA

SHIP TO:
FRED'S GUN EMPORIUM
3003 SLIDE RD
LUBBOCK TX
USA 79407

CUST NO:006566 ILION

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		CLEAN/TEST			UPS

GUN CONDITION
- [ ] NEW
- [ ] LIGHTLY WORN
- [ ] WORN
- [ ] VERY WORN
- [ ] UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1 trigger	B1 goes off when bolt action is closed				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD		-	C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Received w/ stock cracked at mag. box — mfg. 1968. Cannot duplicate complaint — however, sear/trigger assembly is contaminated with a gummy, sticky residue — original trigger parts are not moving freely, nor properly. Sear-safety cam is sticking on side plate of trigger housing — rifle has not been properly maintained. trigger pull 5½ pounds; sear-lift .006"

PARTS

COMMENTS: Based on age of rifle offer replacement trigger assembly at normal cost as a gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATT.
HB					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY RD6925 REV

PPS 01832