

To Whom it may Concern

Purchased This Rifle, in March 1994 From Bill Hicks + Co.

HAS Never been Fired Bolt make a Squeaking Noise. Accidently Dry Fired Twice during operation of bolt, Please Repair and Return to

Gibbs Gun Shop
RR 2 Box 234
Mcher, Ga 30439