RECEIVING AND ESTIMATING REPORT

COMMENTS C6777242 Product Service

ORDER R 94-27501

INITIAL	CUSTOMER ORDER NO.
FFS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
09/26/94	09/27/94	LN 2-93	C67777242		700 22-250 BDL

ACCESSORIES W/STUDS SCOPE BASE L/REAR SIGHT

FROM:

D & R SPORT CENTER
620 FAIRCHILD/200 W UNION
P O BOX 139
NANTICOKE PA 18634

SHIP TO:

D & R SPORT CENTER
620 FAIRCHILD/200 W UNION
P O BOX 139
NANTICOKE PA 18634

CUST NO:007810 WILM

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
	C59015	☐		9-29-94	UPS

GUN CONDITION
- [x] NEW
- [ ] LIGHTLY WORN
- [ ] WORN
- [ ] VERY WORN
- [ ] UNREPAIRABLE
- [ ] MARRED

Rec'd 9/29/94

price to rec'd last

REPAIR CHARGE	20.00
EXCISE	
TAX	
INSURANCE	
UPS	8.00
PARCEL POST	
TOTAL	28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		Fires when the safety is pushed on			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT Mfgr. 2/93 Unable to make gun malfunction as rec'd. Inspected trigger still no fault found. Customer may have inadvertently contacted trigger when operating safety lever. Exchange trigger assy at n/c as a gesture of good will and to restore customer confidence in the rifle.

PARTS Trigger Assy. Complete

COMMENTS Trigger pull measured 3 1/4 to 3 3/4 LBS as rec'd. Sear lift was .02 Sear engagement in spec.

- Shaving brass at ejector plunger hole de burr.
- Bolt Stop Sticks as Rec'd

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
RBS			✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

PS01921