RECEIVING AND ESTIMATING REPORT

COMMENTS: WOG 2 OF 2

Product Service

ORDER: R 95-00091

INITIAL	CUSTOMER ORDER NO
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/20/94	01/03/95	CW 4-77	6550529		700 30-06 BDL

ACCESSORIES: W/STUDS SLOPE BASE L/REAR SIGHT

FROM:
NATALE, MARK
BOX 1014
477 SMITH RD.
TROY MT 59935

SHIP TO:
NATALE, MARK
BOX 1014
477 SMITH RD.
TROY MT 59935

CUST NO:111659 C.B.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM DATE	ESTIMATED	VIA
063103		☐			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☑ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

Sent 1/25/95

to cust clean & test

REPAIR CHARGE	26
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	86

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE						
TRIGGER GROUP					E1	F1
BOLT ASSY.					E2	
BARREL ASSY.					E3	F3
REC. ASSY.						F4
WOOD						F5
METAL						

Wife had gun fire when she pushed the safe to fire position

MAIN FAULT: Mfgr 4/72 Unable to duplicate customer concern as recd pelands pull and sear engagement seems have been altered outside of the factory. NOT RECOMMENDED!

PARTS: trig. Assy.

COMMENTS: trig. pull measured 4¾ to 4½ LBS as recd. sear lift was .008

Also; Rust on trigger and connector as recd.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET
RCP		✓	✓	
GALLERY TESTER	DATE	DATE	DATE	DATE

OFFICE COPY

PS04514