2604 Warwick Dr. NE
Marietta, Georgia 30062
(404) 971-2315

December 8, 1991

Remington Arms Co., Inc.
Box 179
Ilion, NY 13357

Dear Sir,

On a recent hunting trip, my 350 Rem. Mag. model 600 discharged when I pushed the safety forward to unload. The bullet went through the fire wall of my truck and into the engine.

Please advise if this was a malfunction and if your compnay will assume the responsibility of repair to the gun. I have already repaired the damage to the truck.

Sincerely yours,

Howard E. Parker

Howard E. Parker

HEP:elp

RECEIVED
DEC 16 19