Remington Arms Co., Inc.
Product Service
Legal Case #:6739

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
244639	10/25/2011	10/26/2011	10/26/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Gander Mt		Gander Mt	5450 Landers Rd	Sherwood	AR	72117		W 501-945-4070

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern			
S Fired on bolt closing	Concern:1008 Fired on Bolt Closing		Unknown	
C				

11/10/11 Per note with rifle, firearm discharges when closing the bolt.cm

---

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/6MM REM	n/a	A6517687	EO	10/25/1977
Date Purchased	**Where Purchased**	**Accessories**	**Original Owner**			
	ORGILL BROS CO MEMPHIS TN	SCOPE BASE,RINGS,SCOPE	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at BLSM program price						

Repair/Replacement Cost	Repair/Replacement Date
42.40	11/10/2011

11/10/11 Per Ilion, could not duplicate concern. Trigger assm set screws altered. Trigger has min. return. Replace TPA, clean, test fire at BLSM program price of $20 + shipping.cm

---

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		10/26/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 6MM REM
	Date Code		EO
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

PS 23464

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	MARS DENTS
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	HAS MIN TRIG RETURN
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE,RINGS,SCOPE

⊗ GANDER MTN.™

Service Request
Service Order # 7766

6739

SHIPPED TO VENDOR/STORE:

Remington Repair FFL# 6-16-00726
14 Hoefler Ave

Ilion, NY 13357
Attn:
Date Shipped: 10/19/2011   Phone: (800) 243-9700

FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.   Type: Rifle   Serial Number: a6517687
Model: 700   Cal/Ga.: 6mm   Cased?: ☐

DESCRIPTION OF ITEM RETURNED:

remington 700 6mm w/ redfeild scope wide view

REASON FOR RETURN:

firearm discharging when bolt closes

ATTENTION VENDOR
Please contact me with any questions or concerns.
Jerry Tanner
(501) 945-4070

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence:

SHIP TO ABOVE ADDRESS

Forward all invoices to: **Gander Mountain**
                             Attn: Cindy Kilbride
                             PO Box 1224
                             Minneapolis, MN 55440

SHIPPED NOV - 1 PAID

could not duplicate concern
T.A. set screws altered. TR19
has min return. Replace TPA,
clean + test fire under BCP
for $ 20.00 + ship

Quote

A6517687
Model: 700

```
RE00244639
```

PS 23466

PS 23468

PS 23469