RECEIVING AND ESTIMATING REPORT

COMMENTS: ATTN: FRAN COLE

RGO- 31195

INITIAL	CUSTOMER ORDER NO.
FPS	011308

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
11/28/90	12/03/90	EJ 10-89	C6448077	700 7MM LH BDL	R 90-311

ACCESSORIES: W/STUDS SCOPE BASE L/SIGHTS

FROM:
LIVINGSTON SPT CENTER
5589 E M-36 CHILSON RD
LAKELAND MI 48143

SHIP TO:
LIVINGSTON SPT CENTER
5589 E M-36 CHILSON RD
LAKELAND MI
48143

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: ☒ LIKE NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"Customer tells me that on three separate occasions that gun has fired when safety was moved to the fire position".

MAIN FAULT

No fault found - cannot duplicate complaint. Trigger assembly and safety function properly. Trigger pull somewhat heavy at 6#, sear-lift .011"

PARTS

Offer to return rifle as-is or, if it would settle custom faith in the rifle we could install a new trigger assy at ½ normal price, as a gesture of good-will

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7.