RECEIVING AND ESTIMATING REPORT

COMMENTS: ATTN R POTTER W/1 SPENT CASE

ORDER: R 92-03183

INITIAL	CUSTOMER ORDER NO.	DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
JJM		01/20/92	01/27/92	XE 12-84	B6652B14		78 30-06

ACCESSORIES

FROM:
MORTON, FRANKLIN
HC 82 74525
ATOKA OK 74525

SHIP TO:
MORTON, FRANKLIN
HC 82 74525
ATOKA OK 74525

CUST NO:056976 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	See attached letter from customer	B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: As received, trigger assembly and bolt stop were inoperative. Disassembly of rifle revealed trigger assembly and bolt stop to be contaminated with a sticky, gummy substance. The sear-safety cam was stuck to the trigger assembly side-plate & the bolt stop was stuck to the receiver cut. Butt of trigger assembly is also rusted, appears to have had improper tolerance. Trigger pull & sear lift could not be measured.

PARTS	COMMENTS
	Offer replacement trigger assembly & bolt stop as a gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN

GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/9