CUSTOMER ORDER NO.					
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
/30/93	05/03/93	CG 4-86	B6782962		700 30-06 MTN

SSORIES W/STUDS SCOPE BASE

Set up fee

I: ARMY SURPLUS I
501 OAK STREET
SANDPOINT ID 83864

SHIP TO: ARMY SURPLUS I
501 OAK STREET
SANDPOINT ID 83864

CUST NO:078739 C.O.D.

UNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
	059001				UPS

CONDITION		REPAIR CHARGE
IEW		EXCISE
IGHTLY WORN		TAX
VORN		INSURANCE
VERY WORN		UPS
UNREPAIRABLE		PARCEL POST
MARRED		TOTAL

STOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
LE	A1	B1				
GGER GROUP		B2				F1
T ASSY.						
REL ASSY.		B4		D1	E3	F3
. ASSY.		B5		D2	E4	F4
OD			C1	D3	E5	F5
TAL			C2			

Trigger does not fire, then fires upon lifting bolt.

FAULT Unable to duplicate customers concern.
Demonstrated the action, trigger assembly, and bolt stop release. Customer must manually engage safety. Now then manual safe required to engage safety.

ITS	COMMENTS
Sear Lift - .011	Replace complete trigger assembly
Trigger Pull - 5½ lbs.	& clean action at no charge

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
FB.					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92