Pgsi-Products Co Inc
10765 Kinspoint Rd
Houston, Tx 77075

-554077

Remington Arms
ATTN Service Dept
Ilion, New York 13357

RETURN REQUESTED

DATE Jan 27, 1981

REPAIR DEPT.

THE FOLLOWING MERCHANDISE IS RETURNED TO YOU PREPAID. UNDER WARRANTY, FOR REPLACEMENT OR REPAIR, AT NO COST.

THE AMOUNT OF $_____ IS ENCLOSED FOR HANDLING CHARGES AS REQUIRED.

PURCHASE DATE [redacted]

QTY. 1 700 ARTICLE 3006 Bolt Rifle

First while releasing the safety Finger was

[illegible] SN# A6918730

I DESIRE THIS MERCHANDISE BE RETURNED TO ME AT THE FOLLOWING ADDRESS, WITHOUT DELAY:

RETURN TO Pgsi Products Co. Inc.

ADDRESS 10765 Kinspoint Rd

CITY & STATE Houston, Tx. 77075

TELEPHONE 1-713-460530

VERY TRULY YOURS,

LARRY Puccetti
(CUSTOMER SIGNATURE)

ACCOMPANYING CHANGES & POSTAGE.

FORM 23025 REV. 5/77

E.F. Barrett
J.E. Preiser
E.G. Larson
R.B. Sperling
J.H. Chisnall
D.J. Sanita
S

9, 1981

s, Mr. Larry Puccetti, A6918730, which you fety was moved to the

of 1979, has been ex- it contained our high- pection stampings, in- necessary tests prior

good and, in going over al, recoil shoulders

uld not duplicate the and dimensions were gement; also, factory , indicating no al- mpany. Trigger pull

Based on our findings, Remington Arms Company, Inc., cannot accept any liability or responsibility for the incident. It is possible that while your customer was moving the safety lever from the "safe" position to the "fire" position, he, at the same time, inadvertantly contacted the trigger. When the safety lever reached the "fire" position, the gun then discharged - as it is designed to do - because the trigger was being pulled with the gun no longer on "safe".

PPS 00468