RECEIVING AND ESTIMATING REPORT

COMMENTS: ATTN R POTTER

ORDER: R 92-27585

INITIAL	CUSTOMER ORDER NO.
J.JM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/15/92	12/15/92	PL 6-91	C6655033		700 7MMMAG ADL

ACCESSORIES: W/STUDS

FROM:

BLACKBURN, JULIE
418 SW 16TH
PENDLETON OR 97801

SHIP TO:

BLACKBURN, JULIE
418 SW 16TH
PENDLETON OR 97801

CUST NO:071940 C.O.DL

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D1	E4	
WOOD				D3	E5	F5
METAL			C2			

(1) Alleges gun fired w/ safety in fire position w/out pulling trig.

(2) Heavier than normal force required to move safety switch. Bolt release button works hard

MAIN FAULT

~~Bad~~ (1) Could not duplicate accidental firing

(2) Safety switch defective ball/shoe broken

(3) Bolt release button does work hard.

Per customer request replace bolt release button & install new trigger assy with old style bolt lock KHP 12/15/92

PARTS	COMMENTS

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92