RECEIVING AND ESTIMATING REPORT

COMMENTS: BBL CUT OFF OUTSIDE FACTORY SteKL

ORDER: R 92-00150

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/23/91	01/02/92	DZZ 9-53	334873		721 300H&H MAG

ACCESSORIES

FROM:
BOKOR, JOSEPH L
P O BOX 49
BARBEAU MI 49710
USA

SHIP TO:
BOKOR, JOSEPH L
P O BOX 49
BARBEAU MI
USA 49710

CUST NO:055487 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		1-15-92	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.					E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Gun fired when taking Safety off

MAIN FAULT: trigger assembly has been re-adjusted by gunsmith since incident. Disassembly of rifle needed. Trigger assembly is now operating properly. Rifle cannot be made to malfunction at this point.

Trigger pull 3½ pounds, sear lift .011"

PARTS

COMMENTS: Apparently customer would like a non-bolt lock trigger assembly and safety.

Offer new style assembly at ½ normal cost, as a gesture of good-will.

Note rifle is 39 years old!

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
WBoK					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91

PPS 00573