RECEIVING AND ESTIMATING REPORT

COMMENTS: Stell

ORDER: R 92-04099

INITIAL	CUSTOMER ORDER NO.
JJM	F79535

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
01/28/92	02/03/92	KF 5-85	B6587087		700 270 BDL

ACCESSORIES: W/STUDS SCOPE BASE

FROM:
BORDER SPORTING GOODS INC
303 MAHER STREET
LAREDO TX 78041

SHIP TO:
BORDER SPORTING GOODS INC
303 MAHER STREET
LAREDO TX 78041

CUST NO:006546 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		2-25-92	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	Fires	B2 When	Bolt is lefted		E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Cannot duplicate complaint. However, discovered rifle received sear-engagement has been improperly adjusted at factory, as evidenced by factory sealant — sear engagement is excessive.

Trigger pull - 4¾ pounds; sear-lift .013"

PARTS

COMMENTS: Offer new trigger assembly at ½ normal cost, as a gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
RBS					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91