RECEIVING AND ESTIMATING REPORT

COMMENTS: CALL TAG ATTN: DENNIS SANITA

ORDER: R93-21595

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
10/08/93	10/11/93	KY 5-74	6739929		700 308 WIN BDL

ACCESSORIES: W/STUDS SCOPE BASE

FROM:

BRUNK, ROBERT E.
43 CHAPARRAL
KERRIVILLE TX 78028

SHIP TO:

BRUNK, ROBERT E.
43 CHAPARRAL
KERRIVILLE TX 78028

CUST NO:085095 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	25.00
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1 ✓				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Repair of Premature Firing

MAIN FAULT: Upon attempt with cartridge, when closing the bolt assembly, firing pin falls down. Bolt stop when bind up from heavy gummy substance. Also noted was that all 3 engagement areas have been adjusted outside the factory. Our inspection revealed has been removed. The rear engagement has a white colored residue. Action needs a good cleaning.

PARTS:
Date Mfg 1974
Per telephone 11/3/93
Credit Card Visa
4121 2699 8001 2006
4/94

COMMENTS:
Replace complete trigger assembly. Compare and clean action at 1/2 normal operation cost, as gesture of good will.

REPAIRMAN	PROOF	CLEAN	TEST
		✓	✓
GALLERY TESTER	DATE	DATE	DATE