RECEIVING AND ESTIMATING REPORT

COMMENTS: Product Service

ORDER: R 93-24598

INITIAL	CUSTOMER ORDER NO.
JJM	7850

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/09/93	11/14/93	PZ 6-75	6873788		700 300WIN MAG/BDL

ACCESSORIES: W/STUDS SCOPE BASE L/REAR SIGHT

XC F. Supply

FROM:
CHALMETTE JEWELRY & SPTG GOODS
507 W ST BERNARD HWY
CHALMETTE LA 70043

SHIP TO:
CHALMETTE JEWELRY & SPTG GOOI
507 W ST BERNARD HWY
CHALMETTE LA 70043

CUST NO:001988 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
				12-2-93	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	25.0
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE		B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Gun fires when Moving Safety "

MAIN FAULT: Late May 1925 Upon receipt I Unable to duplicate customer concern. Examination revealed that the action and trigger assembly are covered with sticky substance, which has been dripping off the receiver. The bolt stop release is gummed up and does not return. Gun has seen good use

PARTS

COMMENTS: Replace complete trigger assembly & clean action, at 1/2 normal replacement cost, as gesture of good will. Go ahead.

DEPARTMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
WBD					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

V. 1/92

PPS 01000