:CEIVING AND ESTIMATING REPORT

COMMENTS: CALL TAG: ATTN. TOM NAGLE
W/BTM. FRONT HALF OF SCOPE MNT.

ORDER: R 94-16802

CUSTO ER ORDER NO.:

RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
/25/94	05/26/94	WU 8-71	6468752		700 30-06 BDL

SSORIES: SLING STRAP W/STUDS W/SWIVELS SCOPE BASE

M:
COOPER, THOMAS E.
1700 1 WILLIAMS CTR.
TULSA OK 74172

SHIP TO:
COOPER, THOMAS E.
1700 1 WILLIAMS CTR.
TULSA OK
74172

059015 CUST NO:097858 C.O.D

OUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
	059001	☐			UPS

CONDITION	REPAIR CHARGE
IEW	EXCISE
IGHTLY WORN	TAX
VORN	INSURANCE
ERY WORN	UPS
NREPAIRABLE	PARCEL POST
MARRED	TOTAL

TOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
LE	A1	B1				
GER GROUP	"Discharged when safety was released."	B2			E1	F1
ASSY.		B3			E2	F2
REL ASSY.		B4		D1	E3	F3
ASSY.		B5		D2	E4	F4
D			C1	D3	E5	F5
AL			C2			

FAULT Upon receipt, we were unable to duplicate customer's
model. Trigger pull measured at 3.5-4 LBS., gear tight. OIO.
trigger adjusting screw and trigger stop screw have been re-set
Held of factory as sealant is missing. Minimum overtravel
Replace Trigger assembly at n/c to customer as genuine
of good-will. Gun safe 8-71. TV 5-26-94

S

76345

COMMENTS

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

PPS 01184