ESTIMATE OF REPAIR COST

FORD

BOB DYER FORD, INC.

Hwy. 64-70, West — — — — Phone 464-5431
CONOVER, N. C. 28613

Lenoir

NAME	ADDRESS	PHONE	DATE
Roger Dula	Rt 10 Box 505	054-4115	12-9-81

YEAR	MAKE	MODEL	LICENSE No.	COLOR CODE	MTR. No. / SER. No.
84	Ford	Ranger	CAF-951		

REPAIR	REPLACE	DESCRIPTION	LABOR	PARTS & MATERIALS	SUBLET & NET ITEMS
✓		Seat	1.0	—	82.50
✓		Rt Dr Inside & Out (P34)	6.0	—	
	1	" " Trim Panel	0.5	148.38	
	1	Rt Rocker Scuff Plate (Alum.)	0.2	12.05	
		Paint & Mat.	3.4	42.60	
		Customer Paid $10.00 Est. Fee			

FOR OFFICE USE ONLY

THE ABOVE IS AN ESTIMATE BASED ON OUR INSPECTION AND DOES NOT COVER ANY ADDITIONAL PARTS OR LABOR WHICH MAY BE REQUIRED AFTER THE WORK HAS BEEN OPENED UP. OCCASIONALLY AFTER THE WORK HAS STARTED DAMAGED OR BROKEN PARTS ARE DISCOVERED WHICH ARE NOT EVIDENT ON THE FIRST INSPECTION. BECAUSE OF THIS THE ABOVE PRICES ARE NOT GUARANTEED.

NOT RESPONSIBLE FOR FIRE, THEFT OR DAMAGE WHILE VEHICLE IS IN OUR POSSESSION.

SIGNED Clayton Sutton

LABOR @ 24 —	$ 246.40
PARTS	$ 208.02
TAX	$ 10.44
SUBLET AND NET ITEMS	$ 82.50
WRECKER SERVICE	$
TOTAL	$ 565.86