RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 91-25964

INITIAL	CUSTOMER ORDER NO.
LCS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/10/91	12/12/91		6265287		700 7MMMAG BDL

ACCESSORIES W/STUDS

WS 8-692ND TIME

FROM:

HANCZARKY, PETER
47A SKYLINE DR
RD 1
MELROSE NY 12121
USA

SHIP TO:

HANCZARKY, PETER
47A SKYLINE DR
RD 1
MELROSE NY
USA 12121

CUST NO:054688 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP						
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4				F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

"The problem with the gun is as follows: When you load it and close the bolt, the shell automatically goes off."

MAIN FAULT As received, the trigger assembly was inoperable. Upon closing the bolt, the firing pin simply followed down on the cocking cam. Inspection of the trigger assembly revealed it was contaminated with a [illegible] substance, to the point that the sear-safety cam was stuck to the side plate of the trigger assembly. This rifle has not been properly maintained!

PARTS

COMMENTS Clean present trigger assembly, if possible. If not, offer replacement assembly at ½ normal cost, as a gesture of good-will.

NOTE → This rifle is 22 years old!!

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN

GALLERY TESTER	DATE	DATE	DATE	DATE	DATE