RECEIVING AND ESTIMATING REPORT

COMMENTS: ATTN: JIM STEKL

ORDER: R92-17240

INITIAL	CUSTOMER ORDER NO.
FPJ	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE		
08/14/92	08/27/92	LC 2-82	B6374739		700	30-06	BDL

ACCESSORIES: W/STUDS

FROM:
HAWKINS, BOB
RT 1
BOX 50
FAIRMONT WV 26554

SHIP TO:
HAWKINS, BOB
RT 1
BOX 50
FAIRMONT WV 26554

CUST NO:065499 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.						F2
BARREL ASSY.		B4		C1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

"... when I took the safety off to open the bolt the gun fired"

MAIN FAULT: Unable to duplicate complaint — rifle and trigger assembly operate normally as, every respect. Sufficient force made to malfunction.

Trigger pull — 4½ pounds, sear — left, NG"

PARTS

COMMENTS: 1. Offer to return rifle as-is, or, to put factory trigger assembly in rifle at ½ normal cost, as a gesture of good-will

2. New trigger guard at ½ cost also.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN

GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6935 REV. 1/93