F. Supply

RECEIVING AND ESTIMATING REPORT

COMMENTS: CALL TAG FRAN COLE

ORDER: R 94-12574

INITIAL	CUSTOMER ORDER NO.
FJB	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
04/08/94	04/11/94	BW 1-72	6513234		700 30-06 ADL

ACCESSORIES: W/STUDS

L/ REAR SIGHT

FROM:
JACKSON, DON
2206 PEYTON PLACE
DEER PARK TX 77536

SHIP TO:
JACKSON, DON
2206 PEYTON PLACE
DEER PARK TX 77536

CUST NO:095662 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
					UPS

GUN CONDITION
- ☐ NEW
- ☒ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	20.00
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	Discharged when bolt pushed down.	B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Rifle mfg 1972. Upon receipt, we find set trigger contains [illegible] Recommend but sure that the safety engagement cannot be been re-set. trigger pull – 1½ lb
[illegible] -005

PARTS

COMMENTS: Replace broken trigger assembly and clean rifle at 1/2 normal replacement cost as gesture of good will
Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6025 REV. 1/94