Safty wont work & Trigger
Goes off without Pulling
when working Bolt

Rem. 700 30-06
6355141

[redacted] SUPPLY INC
[redacted]

700 ADL
16804
6-12-87
[redacted] VS
[redacted] 4901, 40SH [redacted]
MIDSAN CITY [redacted]
6355141
OT: 7-70
3006
CHECKED BY: [redacted]
APPROVED: [redacted]
APPROVED: [redacted]
APPROVED: [redacted]
APPROVED: [redacted]
DIST ON BRL
RECOIL PAD

SR GOES OFF
KIVE SAFT

COMMENTS: Fire control - worn and lips. Gear safety can stick in down position, excessive grunt in fire control. Replace fire control - change customer.

- Trigger pull 3#
- Gun passes trick test.