RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R91-23830

INITIAL	CUSTOMER ORDER NO.
FPS	A80794

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/18/91	11/21/91	WZ 8-75	6893013		700 30-06 BDL

ACCESSORIES W/STUDS SCOPE BASE L/REAR SIGHT

FROM:

MOORHEAD SCHEELS
505 CENTER AVE
MOORHEAD MN 56560
USA

SHIP TO:

MOORHEAD SCHEELS
505 CENTER AVE
MOORHEAD MN
USA 56560

CUST NO:014820 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		11-26-91	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE						
TRIGGER GROUP		B3			E2	
BOLT ASSY.		B3			E2	
BARREL ASSY.					E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

"Rifle discharged unintentionally, causing approx. 700$ worth of damage to the transmission of a truck. Before discharge, bolt worked very hard customer tried to open bolt unsuccessful, upon closing bolt, rifle discharged."

MAIN FAULT No fault found — rifle operates properly in every respect. Many attempts were made to cause the rifle to fire upon closing the bolt, but it would not malfunction.
Trigger pull 5 pounds; rear-left .0085"

PARTS

COMMENTS Rifle can be returned as-is, or if it will better restore confidence in the gun we can install a new trigger, cheap at ½ normal cost, as a gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
DE					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91

PPS 03534