RECEIVING AND ESTIMATING REPORT

CUST NO: 002733 ILION

COMMENTS: STOCK NOT OF OUR MFG
W/OWNERS MANUAL

TIAL	CUSTOMER ORDER NO.
PS	

TE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
8/05/91	08/09/91	KW 5-72	6555426	700 270 WIN	R 91-15427

CESSORIES: W/STUDS SCOPE BASE
L/REAR SIGHT

ROM:
OUTDOORSMAN
1011 MAIN STREET
HOPKINS MN 55343
USA

SHIP TO:
OUTDOORSMAN
1011 MAIN STREET
HOPKINS MN
USA 55343

COUNT NUMBER	ACCOUNT NUMBER N/C		PROM. DATE	ESTIMATED	VIA
		WRITE ☐ CLEAN/TEST			UPS

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

STOMER'S REQUEST: "Our customer says, several times, the gun has fired when taking it off safety"

AIN FAULT: Cannot duplicate complaint however, it was noted trigger pull movement very slow. Trigger assembly is contaminated with greasy residue. This condition coupled with cold temperatures could cause problems. Trigger assembly has been adjusted outside factory - sealant missing from all adjustment screws.

RTS: Offer replacement trigger assembly at normal cost, as gesture of good-will

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PPS 03735