RECEIVING AND ESTIMATING REPORT

CUST NO:052054 C.O.D

COMMENTS: BBC NOT OUR MFG

TIAL: CS

CUSTOMER ORDER NO.:

TE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE			ORDER
0/28/91	10/31/91		A6398040	700	243	ADL	R 91-22003

CESSORIES: W/STUDS SCOPE BASE

ROM:

POLUPSKY, CLIFFORD
1821 DOREGON
GRAND FORKS AFB ND 58204
USA

SHIP TO:

POLUPSKY, CLIFFORD
1821 DOREGON
GRAND FORKS AFB ND
USA 58204

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					UPS

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

STOMER'S REQUEST: 1.) "My 700 has fired upon closing of the bolt and also when put on fire." 2.) "has trouble chambering from a full magazine 3.) Please send owner's manual & catalogs

IN FAULT: 1.) Trigger assembly has been improperly adjusted outside factory (foreign contact on all adjusting screws) - excessive over-travel, insufficient sear-engagement. Last closing of bolt causes firing pin to fall. 2) Rifle has been re-barreled and highly modified — improper magazine box - follower has been grounded. Forward pull 3½#; Sear-lift .008"

RTS:

1.) send quotation for new trigger assembly
2) " " " proper magazine parts.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PPS 03957