RECEIVING AND ESTIMATING REPORT

ORDER R92-15318

COMMENTS: L/FLOOR PLATE, SCREWS
ATTN: HERB BROWN

ITIAL	CUSTOMER ORDER NO.
PS	

ATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
7/17/92	07/29/92	KS 5-69	6239535		700 243 WIN VAR

CCESSORIES: L/WOOD L/FOLLOWER L/MAG SPRING L/REAR SIGHT

OM:
SHRIVER, ROBERT E
1605 HUFFMAN DR
WARREN OH 44481

SHIP TO:
SHRIVER, ROBERT E
1605 HUFFMAN DR
WARREN OH 44481

CUST NO:064241 C.O.D

CCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST			UPS

N CONDITION
- NEW
- LIGHTLY WORN
- WORN
- VERY WORN
- UNREPAIRABLE
- MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

USTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
YCLE	A1					
IGGER GROUP		B2			E1	F1
OLT ASSY.		B3			E2	F2
ARREL ASSY.		B4		D1	E3	F3
EC. ASSY.		B5		D2	E4	F4
OOD			C1	D3	E5	F5
ETAL			C2			

N FAULT: Trigger assembly has been improperly adjusted outside factory. Sealant is missing from pull adjustment and over-travel screws. Should work but could be duplicated, because trigger pull was measured as light (2 pounds) was no hesitation, spring force light to keep trigger under sear safety. Trigger pull 2 1/4 pounds light. OOS

Note - Customer request O.S. Safety

RTS

COMMENTS: Have adjusted present trigger assembly to our minimum spec - 3½ pounds, 1oz.

2/ Offer new trigger assembly at the normal cost as gesture of good will, set at 3½ pounds

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTE
KB					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1

PPS 04534