RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 92-23741

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/03/92	11/06/92	KI 5-76	6337512		700 25-06 BDL

ACCESSORIES W/STUDS L/SIGHTS

FROM:

SMITH GUNS
5458 PADRE STAPLES MALL
CORPUS CHRISTI TX 78411

SHIP TO:

SMITH GUNS
5458 PADRE STAPLES MALL
CORPUS CHRISTI TX 78411

CUST NO:033393 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3				F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT The rifle is generally poor condition. Many of the metal parts are rusted, including the trigger assembly interior. Internal trigger parts do not moving freely, nor moving properly — at times bolt will not cock because of rusty condition of trigger assembly. Trigger pull 6 pounds; sear lift .009"

PARTS

COMMENTS
1) send quotation for re-blue, as requested
2) Offer new trigger assembly at ½ normal cost, as gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
B.W.					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/9

PPS 04601