P.O. #: [illegible] REMANUFACTURE REPORT NUMBER: 653 MODEL: 700 BDL

GENERAL CORRECTION: PAIR S/N: 03521

CUSTOMER NAME: A SIGHT REMODEL DATE: 2-23-92

FROM: THE SIGHT CENTER
118 N. [illegible] ST
NATCHEZ MISS

FIRED AND TYPE: NOT FIRED

A CORRECTION: CUS #: 6820411
XP=12-94
BDL=1-87

FIRE: RRP DIST.: 90 TIME: 81 CODE:

CHECKED: OK GA./CAL.: 243

BARREL CHECKED: OK CHECKED BY: M HARDY

BARREL REMOVED: OK APPROVED: [illegible] 4/13/92

CHECKED: OK APPROVED: [illegible] 4/13/92

TEST: APPROVED: [illegible] 4/13/92

CUSTOMER CORRECTION: (Damaged, Broken, Old Style) APPROVED: [illegible]

SIGHT WAS SO LOOSE, SCREWING ON RIGHT WORK.

COMPLAINT: CO DOES WHY SAFETY WAS REPLACED AND NOT RE-WORKED

INCIDENT:

COMMENTS: Unable to duplicate customer complaint
- Hit Trigger Pull
- OK on Trick Test
- .019 Sear Engagement
- Normal tension of trigger housing
Replace Sear & Sear Action - No charge.
[illegible] 4/13/92