RECEIVING AND ESTIMATING REPORT

COMMENTS: W/OWNERS MANUAL

R ORDER 94-12838

INITIAL	CUSTOMER ORDER NO.
FPS	T22403

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
04/13/94	04/13/94	KJ 5-89	C6380637		700 270 WIN ADL

ACCESSORIES: W/STUDS

FROM:
SPORTS WORLD
5800 S LEWIS STE 154
TULSA OK 74105

SHIP TO:
SPORTS WORLD
5800 S LEWIS STE 154
TULSA OK 74105

CUST NO:005259 WILML

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
	059001	☐			UPS

GUN CONDITION
- ☑ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

* Safety detent ball sporadically may have come off

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2	Bad safety	– safety come	D1	E1
BOLT ASSY.		B3			E2	F2 off
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Mfgr 5-89 Unable to determine customers concern - safety and trigger assy. work correctly in every respect.

PARTS

COMMENTS: Trigger pull measured 4 to 4 1/4 lbs. as recd. sear lift was .0115 Check for all safety functions and gallery test prior to return

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
TAL		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

PPS 04767