RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 91-23815

INITIAL	CUSTOMER ORDER NO.
FPS	01206999

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/18/91	11/21/91	ED 10-83	B6497676		700 7MM MAG ADL

ACCESSORIES W/STUDS SCOPE BASE

FROM:
WAL MART 206
1670 W UNIVERSITY
MCKINNEY TX 75069
USA

SHIP TO:
WAL MART 206
1670 W UNIVERSITY
MCKINNEY TX
USA 75069

CUST NO:053351 WILM

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	"Fires"	B1 When	Round	Chambered.		
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT Cannot duplicate complaint. However, disassembly of rifle reveals trigger assembly is contaminated with gummy residue, sear-safety cam resists movement of side-plate, bolt stop is ineffective (sticky). Also, trigger assembly has been adjusted outside factory — hi-excessive sear-engagement.
Trigger pull 4¼ pounds; sear-lift .0095"

PARTS

COMMENTS Since sear engagement has been altered, offer new trigger assembly at ½ normal cost, as a gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
ML					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91

PPS 05266