RECEIVING AND ESTIMATING REPORT

COMMENTS

R ORDER 94-10748

Product Service

INITIAL	CUSTOMER ORDER NO.
FDC	0691

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
03/24/94	03/24/94	WN 8/93	C6830972		700 243WIN. ADL

ACCESSORIES: W/STUDS

FROM:
WAL MART 151
ATTN STONEY-CLAIMS
US HWY 69 BYPASS
MCALESTER OK

SHIP TO:
WAL MART 151
ATTN STONEY-CLAIMS
US HWY 69 BYPASS
MCALESTER OK 74501

CUST NO. [illegible] WILML

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
	C59001	☐			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☒ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP ✓		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.					E3	
REC. ASSY.		B5		D1	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

After firing safety would lock up and would not shut when safety was placed on fire "

MAIN FAULT: Unable to duplicate the concern. Safety works as designed. The lock up's would not fire condition noted. The trigger assembly was completely disassembled and cleaned, lubricated. All appears normal. Now functions as designed.

PARTS

COMMENTS: Replace complete trigger assembly, because original has been disassembled.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

PPS 05303