RECEIVING AND ESTIMATING REPORT

COMMENTS F. Supply
ATTN. DENNIS SANITA TRIGGER PROBLEMS

ORDER R 94-13499

INITIAL A. | CUSTOMER ORDER NO.

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
04/18/94	04/19/94	FY 06-74	6755900		700 30-06 ADL

ACCESSORIES W/STUDS

FROM:
WILLIAMSON PRECISION GUNSMG
117 W PIPELINE RD
HURST TX 76053

SHIP TO:
WILLIAMSON PRECISION GUNSMG
117 W PIPELINE RD
HURST TX 76053

CUST NO:006402 ILION

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
					UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☑ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☑ MARRED

REPAIR CHARGE	15.00
EXCISE	
TAX	
INSURANCE	
UPS	8.00
PARCEL POST	
TOTAL	23.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	1) Fired when locking safety after firing					
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.	2) Fired when bolt was closed					F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT Mfgr 6/74 Unable to duplicate customers concern as rec'd.. TRIGGER, connector and sear were gummed up with tacky, gummy lubricant almost schellac like. TRIGGER ASSY. only REQUIRES light lubricant like Rem Oil to prevent rusting. A FILM OF spc/pnc NON HARDENING Replace trigger assy. at [redacted] as gesture of good will and to Restore customers confidence

PARTS

COMMENTS Sear lift measured .010 as rec'd and trigger pull measured 5 to 5 1/2 LBS

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

PPS 05520