RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 93-19414

INITIAL	CUSTOMER ORDER NO.
J.JM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
09/14/93	09/17/93	BW 1-72	6495836		700 25-06 ADL

ACCESSORIES W/STUDS SCOPE BASE L/SIGHTS

FROM:

ALLISON & CAREY GUN WORKS
17311 SE STARK
PORTLAND OR 97233

SHIP TO:

ALLISON & CAREY GUN WORKS
17311 SE STARK
PORTLAND OR
97233

CUST NO:005292 ILIONL

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

Product Service
Complaining that Gun fired when Taking off Safe

REPAIR CHARGE	25.0
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Effective May 1992 Upon accept unable to duplicate Customer Concern. However, examination revealed that the action, trigger assembly, & bolt stop release can cycled with out fitting safety engaged. But release not actuating, trigger assembly stop screw and adjustment screw have had the safety disengaged. Adjustments have been made restore the safety

PARTS

COMMENTS

Replace complete trigger assembly clean action at 1/2 normal cost, as gesture of good will

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		✓	✓		

GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

Go ahead

OFFICE COPY

RD6925 REV. 1/

PS00482