RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 93-12221

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
05/19/93	05/21/93	EA 5-80	A6893874		700 22-250 BDL

ACCESSORIES W/STUDS SCOPE BASE L/SIGHTS

FROM: Setup full

BLUE RIDGE SPTG SUPPLIES
620 CHAPMAN ST
P O BOX 1537
SALEM VA 24153

SHIP TO:

BLUE RIDGE SPTG SUPPLIES
620 CHAPMAN ST
P O BOX 1537
SALEM VA 24153

CUST NO:040723 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.					E2	
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.				D2		F4
WOOD			C1	D3	E5	F5
METAL			C2			

"Will sometimes fire when chamber is split"
"Only happens after trigger pull"

MAIN FAULT Upon request, bolt stop release inoperative. It is gummed up w/ a sticky substance. Action has been given solid wood trigger assy. Unable to duplicate customer concern. Trigger assembly has been cleaned with mineral spirits, excess removed from trigger adjustment & reassembled.

PARTS Trigger Pull - 3 lbs
Sear Bite - .010

COMMENTS Replace complete trigger assy. at 1/2 normal replacement cost & clean action, at price of good work.

Go Ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
FB.		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PS00929